








A - Reset position (with Lock)  
 B - Operation port 21  
 C - Operation port 22  
 D - Operation port 23  
 E - Lamp for PTO insert indication

1 - Energy supply  
 21 - Control lowering  
 22 - Control tipping  
 23 - Engagement Power Take-off  
 3 - Exhaust



| Main Data                |                 |
|--------------------------|-----------------|
| Working medium           | Air             |
| Operating pressure (Bar) | up to 12        |
| Working temperature      | -40 °C / +80 °C |
| Thread Ports             | G1/8"           |
| Operating Light voltage  | 24              |

|                   |           |              |          |       |      |
|-------------------|-----------|--------------|----------|-------|------|
| Copyright WABDEX® |           |              |          |       |      |
| Date              | Signature |              |          |       |      |
| Drawn             |           |              |          |       |      |
| 2025-5-15         | Ahmet     |              |          |       |      |
| Checked           |           |              |          |       |      |
| 2025-5-15         | Furkan    |              |          |       |      |
| Expert            |           | Material No. | Sheet    | Scale | Size |
| Furkan            |           |              | 1/1      | 1:2   | A3   |
| CAD System        | Revision  |              | Language | Mass  |      |
| SOLIDWORKS        |           |              | EN       |       |      |

1:2